

25 JAN 1930

(Received at London Office 19...)

No. _____ Place 130/132 Leadenhall St. Date 24th January 1930.
London, E.C.3.

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to inspect two cylindrical tanks under water pressure at Messrs. Fraser & Fraser, Ltd., Bromley-by-Bow, E. These tanks are being supplied in connection with the Oil Burning Installation for the s.s. LA MAREA now at Workman Clark (1928) Ltd. Belfast. The date on which these tanks will be ready for inspection will be communicated to you later.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

For TODD OIL BURNERS LIMITED

Workman Clark

To the Secretary,

Lloyd's Register of Shipping,
71, Fenchurch Street, London. E.C.3.



002038-002050-0201

Steel Sec. Varies in La Marea.

ack



© 2020

Lloyd's Register
Foundation

Identification Marks

Tube shaft, Material

Identification Marks

... 1-2 Outer hubline bearing; 1-2 outer shaft bearing.