

S. S. "Hebides"

Glasgow Report 16134

It is submitted that before dealing with this case the Surveyor should be requested to state whether bilge pump suction has been fitted in the engine-room & holds, in accordance with the Rules as there are none mentioned on his Report.

Dis Rpt for 7/6/98



© 2020

Lloyd's Register
Foundation
7.6.98

002051-002061-0208