

2m.8.51.

REEBOARD REPORT on the HOLDERNIBD.

Office  
 It is submitted the Hull All referred to this morning ~~telegram~~ telephone conversation and be informed in confirmation thereof that there is no information in this office regarding timber fittings ~~already~~ on board the ship and that it cannot be ascertained from the plans if the vessel has the necessary longitudinal subdivision of the double bottom in the plans are very sketchy.

The Surveyor will require to ascertain these particulars by inspection at the ship and it should be noted that a ship may carry timber deck cargo ~~freight~~ although she is not ~~not~~ marked with timber deck cargo ~~freight~~ marks.

They should be requested to inform the Office if the ~~freight~~ cargo has a clear bulkhead filled with a hinged steel door.

Lloyd's Register  
 Foundation  
 8-1-52