

REPORT on the

S.S. no 177. Hawthorn & Co. Keith

This Submitted the Surveyor he informed that the under-deck tonnage given on his report appears to be too small, giving a corrected Tonnage Coefficient of about .64 instead of .72 as given on the report, and he should verify these figures and report to this office for the provisional freeboard assignment.

Wad

ERM

17.3.19



© 2020

Lloyd's Register
Foundation

002079-002084-0227

2 " 9 1/4