

"DONA LOURDES"

This ship was built at Glasgow in 1919-6 and then classed ~~100A1~~.

The class was withdrawn with a red line 22.6.54.

The HONG KONG Surveyors in a cablegram received 26.6.54 request that reinstatement of class be confirmed.

SUBMITTED the Owners, through the Hong Kong Surveyors be informed that to have the ship's character reinstated in the Register Book as formerly, it will be necessary for:-

- (1) The requirements of a SPECIAL SURVEY (C) to be complied with, including a drilling of the structure, if necessary, where signs of wastage are evident (ship 35 years old).
- (2) Any major repairs which have been effected to the structure since the ship was disclassed to be specially examined in order to ascertain the character of the workmanship and confirm that the materials used are in accordance with the Rules.
- (3) Structural alterations which may have been carried out since the ship's class lapsed and which affect the longitudinal and/or transverse strength of the ship to be reported, and
- (4) Full particulars of the equipment on board, including weights, tests, etc. of anchors and tests, etc. of chain cable to be furnished.

No ship has
been out of
class
4 days
RC

Shah

26.6.54.



© 2020

Lloyd's Register
Foundation

002094-002100-0373