

"DONA LOURDES"

The year of grace having expired 1,54, the maintenance of class is submitted for the consideration of the Committee.

With regard to equipment it is considered that provided the 2 bower anchors and 140 fathoms $2\frac{1}{2}$ " chain cable now proposed to be placed on board be specially examined and found in good condition, and also that the length of cable on board will not be less than required by the Rules, this might be accepted as a temporary measure until completion of the Special Survey on arrival in Japan.



11.6.54.



© 2020

Lloyd's Register
Foundation

002094-0021000382