

AIR MAIL

L. BARBER LIMITED.
CASABLANCA.

TELEGRAMMES: "BARIMER" CASABLANCA.
CODES: ACME, BOE, LOMBARD,
BENTLEYS, A.B.C. 6TH.

BUREAUX: 119 AVENUE DU GÉNÉRAL DRUDE.

REGISTRE DE COMMERCE N° 2991 CASABLANCA.
COMPTE CHÈQUES POSTAUX N° 1421 RABAT.



TÉLÉPHONE (14-65.
14-66.
14-67.)

Casablanca, 10th. May, 1948

(Boîte Postale 420)

DEPARTMENT	RÉFÉRENCE
LLOYDS R.	WP/HC

Lloyd's Register of Shipping
71,enchurch Street
London E.C. 3

RECEIVED

2 MAY 1948

ANSD...

X see cab to 10/5

Dear Sirs,

ss " CAID ALLAL "

We confirm our letter of the 3rd. inst., and our
urgent cable as per copy enclosed herein .

You will no doubt have understood that difficulties
are being experienced by Owners regarding the possibility of
finding stringer plates measuring the required length(as original
plates).

We understand that for some time now the Chantiers
Navals Huyghe who undertook to effect the repairs were prepared
to supply the required length plates, and not until the 7th.
inst. when two joined plates of 3 metres each were sent on board
to replace some of the plates which had already been removed ,did
they inform the owners that they could not actually supply longer
plates . In view of this, Owners have stopped work, pending your
decision as to whether it would be acceptable by you for the
utilisation of 3 metres plates, welded to the required length.


In the opinion of our Surveyor, Mr. Bachellerie,
technically speaking, welded plates could be used quite as well,
but he would prefer to have your authority before committing
himself.

We hope to receive your reply as early as possible
as some of the stringer plates have already been removed, and
work on the vessel is at a standstill.

Yours faithfully.
L. BARBER LIMITED.

W. Pons

W. Pons.



Lloyd's Register
Foundation

002101-002108-0009

Referred to the Chief Ship Surveyor,

Referred to Mr. ~~Smith~~

Jervis

8/11



© 2020
Lloyd's Register
Foundation

RECEIVED

PAQ 1715

1715

1715