

CABLEGRAMS: NYMDIBLE, NEW YORK.

TELEPHONES $\left\{ \begin{array}{l} 220 \\ 221 \\ 222 \end{array} \right\}$ WHITEHALL

LLOYD'S REGISTER OF SHIPPING,

17 BATTERY PLACE,

LLOYD'S REGISTER

LONDON.

NEW YORK, February 2nd, 1921.

REC'D 11 FEB 1921

NSD

Dear Mr. Mayne,

With reference to your letter of the 20th ultimo and to Boston Report No. 1430 on the Steamer "REAPER", I attach hereto a letter dated 1st instant received from the Surveyors from which it will be seen that the thickness of the 2nd deck plate is as approved and that the number of rivets in No. 5 longitudinal bulkhead brackets is 10 and not 9 as shown in the report.

Yours faithfully,

F. A. Mayne, Esq.,

London.

RPH/RT



© 2020

Lloyd's Register
Foundation

002101-002108-0171

Referred to Mr. Mayo.

M

7A M.

11/2/21

M
18.24

W. H. H. H. H.

W. H. H. H. H.

trooper end of work

Atos edit to rettel troy of ederefer nain
temsets edit no OSL. On troper notsoe of tne onitlin
trastani tel betab rettel a otered hostas I, 77777777
ed lliw ti dohnt more stroy eritns end wort bevider
as ai etalq keeb bus edit to asenclolnt end tadt asce
3. On ni atevir to redmum edit tadt bus beverger
as e ton bus Ol ai atekerd baedklwd lenibnditknol

..ped .entpax .L .T
..nohnd

PE/HEP



© 2020

Lloyd's Register
Foundation