

LLOYD'S REGISTER OF SHIPPING,

89 STATE STREET,

BOSTON (9,) MASS.

*[Handwritten signature]*

*[Handwritten initials]*

February 1, 1921

LLOYD'S REGISTER  
NEW YORK

REC'D FEB - 2 1921

~~ANS'D~~

The Secretary,  
New York, N.Y.

*[Handwritten initials]*

Dear Sir,

In answer to your letter of January 31, having reference to our report #1430 on the steamer "REAPER" we beg to advise you that the thickness of the 2nd deck plating is as approved, and with regard to the number of rivets in No. 5 longitudinal bulkhead brackets, we much regret that an error was made in the report and the number of rivets referred to should be 10, in place of 9 as reported.

Yours very truly,

*Wm. Stewart*

For the Surveyors.

*[Handwritten initials]*



© 2020

Lloyd's Register  
Foundation