

Steering Gear, Type (Power or hand) Hand ✓

Alternative Means of Steering Blocks r

Groningen district.

(Req. 1a.)

(Received at London Office

19

No. 125 Place Westerbroek. Date 8-2- 1950.

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 260 building by Messrs. G.J.v.d.Werff's Scheepsbouw for ~~Messrs.~~ Mr. S. Boudewijn of 400 Tons. Length 43.00 M., Breadth 7.65 M., Depth 3.15 M. intended to be Classed +100A1.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers M.A.N., Augsburg.

Boiler Makers -

Signature

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

COMM. VENN.
G.J.v.d.WERFF's
SCHEEPSBOUW

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

Auth. 17h
002158-002150-0153
Steering gear, windows and auxiliary steering gear have been tested to satisfy
All tanks, w.t. bulkheads & decks have been tested and found tight. ✓