

Extensive reconditioning of machinery has been carried out at Baltimore, but the following departures from the Rules have been noted.

Expire Clogs

Submitted to the Surveyors
asked to return the deferred reports and
to indicate the nature of the Machinery
Survey now in hand at that port.

GA

18/4/43

© 2020

002184-002193-0018

ing replaced with Approved Safety Valves of Rule size when the
Emergency is over.

Electric Welding Repairs to "D" Shaped Inboard Water Drums of