

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME St Se. " LONDON QUEEN, Rpt. Lth. No. 18353,

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

¹/₂ Long
Transverse No. 2813

Depth "d" 11.8 1/2 U.D.Framing: Table No. 1Description Bulb angle frames as approved.

²/₊ Longitudinal No. 8745

Proportions $\frac{\text{Length}}{\text{Depth}} = \frac{13.38 1/2 \text{ U.D.}}{\quad}$

~~Deck~~ Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100 A. I. (Steel).

1 D^k (Stl) Well D^k.

Cell D.B. + 124' 196t, F.P.T. 57t, A.P.T. 34t.

B.K 7", 3 B.H., Cem, Lays A.T.P.

Q 110', B 114', F 25'.

machy aft.

The Certificate of Classification to be endorsed "Cargo battens not fitted" and the same notation to be printed in the Register Book.

It is included the riveting of the hulls of the bridge side plating as required by the Rules but the surveyor should state if this is so.



© 2020

Lloyd's Register
Foundation

3/33
3/31