

Sunderland Licence No. 2148. see SUNDERLAND RPT. NO 34721

Req. 1.

(Received at London Office,.....)

No. \_\_\_\_\_ Port Sunderland, Date Sept 11<sup>th</sup> 1946.  
We request that the portion of the Iron Scaffolding  
on the Tanker "Armeda" Building  
for Anglo Saxon Petroleum Co. Ltd. by Joseph L. Thompson & Sons Ltd.  
of \_\_\_\_\_ Tons. Length, 337.0 breadth, 50.0 depth, 19.3  
may be Specially Surveyed while building ( 100. A. I. ) If for a particular term  
or class, state the same.

We hereby engage to pay the established Special Survey Fees as set forth in the Society's Rules, or  
any variation therefrom which has been duly notified and, in addition, any travelling and other expenses  
which may be incurred by the Surveyors in connection with the survey.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping,  
which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be  
held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register  
Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member  
thereof, or the Surveyors, or other Officers or Agents of the Society."

No. 546 in Builder's Yard. Manufacturers of Engines \_\_\_\_\_

Ditto of Boilers \_\_\_\_\_

FOR AND ON BEHALF OF  
JOSEPH L. THOMPSON & SONS, LIMITED.

Signature \_\_\_\_\_

To the Secretary,  
Lloyd's Register of Shipping,  
71, Fenchurch Street, London, E.C.3.

GENERAL MANAGER

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

002206-002214-0171