

COPY.

Lloyd's Register of Shipping.

Port

SUNDERLAND.

11th July, 1947,

This is to Certify that I have

Surveyed the Boiler and Machinery of the Twin Screw Motor Vessel
 "ARMILLA", 3384.85 tons gross of 's Gravenhage whilst lying
 afloat and in dry dock at Messrs. T.W.Greenwell & Co., Ltd., Sunderland

and that I have transmitted to the Committee of Lloyd's
 Register of Shipping, London, a Report stating that all
 recommendations made by me in connection therewith have
 been carried out to my satisfaction, and that I have

Recommended that the record of Survey LMC CS 7.47. DBS 7.47
 and port and starboard screwshafts (CL) seen P.5.47., S.N. 5.47.,


be made in the Register Book in the case of this vessel ~~where~~
~~the survey has been completed.~~

Parts now examined:—

Port and Starboard Engines:— All cylinder liners, pistons, rods,
 covers, valves and gear and supercharge casings.
 All crossheads, guides, crankpins and brasses, journals
 and bearings, thrust and intermediate shafts,
 attached pumps with valves and connections,
 compressor cylinder liners, pistons, rods, covers,
 valves, crankpin and journal

Auxiliaries:—

Kromhout engine (2 cyl.) with attached compressor
 all parts complete.
 Kromhout engine (1 cyl.) all parts complete.
 Steam Generator with attached emergency
 compressor all parts complete.
 All Auxiliary pumps.
 All starting and injection air receivers cleaned
 and examined internally.



continued.....

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
 executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
 whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
 entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
 Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Twin Screw Motor Vessel "ARMILLA".

All main and auxiliary intercoolers,
 lubricating oil and water coolers cleaned and tested.
 Daily service tank cleaned and examined
 internally.
 Condenser tested. Steam pipes tested.
 Pumping arrangements, oil fuel burning
 installation.
 Windlass and steering engine.
 Sea connections.
 Electrical installation.
 Propellers outer end of stem bushes and
 outside fastenings of sea connections.

A. E. Munro.

ENGINEER SURVEYOR TO LLOYD'S REGISTER.



© 2020

Lloyd's Register
 Foundation

002206-002214-0175 ²/₂