

5 Jan. 7, 42. Swan, Hunter & Wigham Richardson Ltd., Newcastle-on-Tyne, Yd. No. 1724 **F.E.**

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME Motor Tanker "BRITISH RESPECT" REPORT Nwc. No. 101186

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 15760

Depth "d" -

2nd Long. No. 44350

Proportions =  $\frac{L}{D}$  13.60

Framing As approved

Sheerstrake As approved.

Two longitudinal bulkheads are fitted

This vessel is similar to the "BRITISH INFLUENCE", "BRITISH HARMONY", "BRITISH CHARACTER" & "BRITISH GRATITUDE".

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ~~100A1~~ "Carrying Petroleum in bulk"

1 Dk, 2nd dk clear if cargo tanks. "Longitudinal framing at bottom and at deck"  
"Butts of shell and deck plating electrically welded"

Cell DBa 75' 170t, DTf 32' 313t, FPT 149t, APT 82t

FK, 16BH, Lloyd's A & CP

P 102' B 46' F 49'

Mchy Aft

O.L. 486.3'

E.S.D.

d+

The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L: (A bower anchor and 60 fathoms chain cable to be supplied).

*added*

*Not an Aircraft Carrier*



*f.c. 2*  
*both*  
© 2021  
10.5.43

Lloyd's Register  
Foundation

002222-002228-0191