

**COPY**

Phl.8732

"FOZ DO DOURO"

New heavy oil engines which were not constructed under Special Survey have been fitted in this Sailing Vessel in accordance with the approved plans and the Requirements of the Rules and

Records LMC 11.45 DBS 11.45 S 11.45 NE.45 have been assigned by the American Committee.

Calculations for torsional stresses in the shafting have been submitted and on investigation have been found satisfactory provided a notice board be fitted at the control station in the engine room stating that the engines of this vessel must not be run continuously between 130 and 150 r.p.m.

IT IS SUBMITTED the Records assigned by the American Committee be confirmed and the New York <sup>h</sup> *Lisbon* Surveyors informed of the above requirement.

*The vessel's class be made subject to the engines not being run continuously between 130 & 150 r.p.m.*

*Reh.*

10.1.46.

*932/1*



© 2020

Lloyd's Register  
Foundation

001232-00240-0316