

Less Engine Room 6450.87
Less Navigation Spaces 173.48

" "

Upper Deck at side
to top of keel

16.6

Port belonging to

Liverpool

COPY.

GRAMS: REGISTER LIVERPOOL.

TELEPHONE: CENTRAL 5281 & 5282.



Lloyd's Register of Shipping.

201, Tower Building,

Liverpool, 9th June 1923

LLOYD'S REGISTER,
LONDON.

REC^d 11 JUN 1923

ANS^d

Dear Mr. Hill,

With reference to your letter of the 8th instant addressed to Mr. Clark, who is away on holiday, respecting the S.S. "FRANCONIA" I have to say that the Surveyor states that the steering gear has now been overhauled and put in working order.

With kind regards

Yours faithfully.

L. R. Hatton.

J. F. Hill, Esq

LONDON. E.C.

2m, 11.21.-T.

002241-002248-0007

002241-002248-0013

C. DK

Tee Bulb or Channel
Angles on upper edge

Angle, Plate, }
9x 3 1/2 x 3 1/2 x 40

9x 3 1/2 x 3 1/2 x 40

9x 3 1/2 x 3 1/2 x 40

B. DK

Angle on ditto
Tie Plates

Deck Material and thickness

6x6x.8

Referred to the Chief Ship Surveyor

Last date
of survey 8/6
per Mr. Mayne

11 JUN 1923

[Signature]
Report
11/6/23

[Signature]

[Signature]

Chief Ship Surveyor

Surveyor Extraordinary

CHIEF SURVEYOR

CHIEF SURVEYOR



© 2020

Lloyd's Register
Foundation

Engine Room
Tonnage for PE
Less Engine Room
Less Navigation S

Des

No.

you
of
sea

tank
but
Sur

land
what
fuel

The

C. OK
Ang

2m. 11.21.