

REPORT OF SURVEY FOR REPAIRS, &c.

Writing Report 2-4-1942 When handed in at Local Office 19 Port of Buraco, Z.W.I.
 Survey held at Buraco, Z.W.I. Date, First Survey 23-10-41 Last Survey 2-4-1942
 on the ~~Wood, Iron or Steel~~ S.S. m.v. "St. Eustachius" ex. "Koribia" (No. of Visits 12)

NAME: Built at Klein Hanskang. By whom A.F. Volcanoff When 1921
 Owner Grauert Schepman & Mutsaers Owners' Address Buraco, Z.W.I.
 Managers _____ Port belonging to Willemstad.

Keel Afloat or in Dry Dock? Afloat Name of Dock Apr. Wap & Boney. Destined Voyage _____
 Depth of Water _____ feet; uE&B _____ feet; f _____ feet
 Capacity _____ tons. FPT _____ tons; APT _____ tons; MT _____ feet _____ tons.

Report, No. 2090 Port Buraco, Z.W.I.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER: * for Special Survey, Date of last Survey and of Periodical Surveys.
 Machinery and Boiler Surveys (including date of N.B., in any).
Classification Survey
Leaking Sulphuric Acid in portable cylindrical tanks between Buraco and Buraco, Z.W.I.
 Society's Freeboard (if assigned) as painted on Ship and now verified _____ ft. _____ ins.

Special Surveys, when held, must be reported in detail and seriatim in the terms of the Rules and items remaining to be done. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters relating to this case.

Was a damage report made by anyone else? If so, by whom? _____
 REPAIRS, OR EXAMINATION AS PER RULE, FOR Classification & S.S. 2nd Part.
Done: Welding of circular seam of upper acid tank completed, tank with all membranes tested to 70 L/P and found satisfactory. The Owners have not yet been able to place equipment in accordance with the letter 'g' of the Rules nor have the steering chains tested, this will be done at the first opportunity.

OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Surveyed								
Moved and Paired or Repaired								
Repaired or Replaced in place								

CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M. (State if on Felt.)
Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	When fitted, Month _____ Year _____
Fastenings	Cement or Asphalt	Oil Bunkers	Boats
Steering	Rudder	Scuppers	Masts, Yards, &c.
in way of sidelights	Steering gear and its connections	Cargo Hatchways	Condition, how ascertained (State if wedges removed)
Names	Windlass	Hatches	Equipment letter
Valves	Have pumps been examined and found efficient?	Planking	Anchors, No. of _____
Water-tight Doors	Have Sluice Valves been examined and found efficient?	Caulking	Cables (State if now ranged)
Ventilators and their Coamings	Have Water-tight Doors been examined and found efficient?	Treenails	length _____ mean diam. _____ (on board)
Plating	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Rule length _____ size _____
Paints	Have Ventilators and their Coamings been examined and found efficient?	Transoms, Pointers & Crutches	Chain Locker
Internal	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings	Hawsers & Warps
Internal	Have Ventilators and their Coamings been examined and found efficient?	Stringers, Clamps & Shelves	Standing and Running Rigging
Internal	Have Ventilators and their Coamings been examined and found efficient?	Salting (State if examined.)	Sails

General Observations, Opinion as to Class, Recommendation, &c.:—
 State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon the survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."
Vessel, so far as now seen is eligible in my opinion, to be assigned the notation class contemplated, Special Survey 23-10-41 and record of Survey 10-41, as previously recommended, when the equipment has been placed in accordance with the requirements

(per Section 29) _____ £	Fees applied for, _____
Age or Repair Fee (if any) _____ £	19 _____
Expenses (if chargeable) _____ £	Received by me, _____
Surveyor's Fee (if any) _____ £	19 _____

[Signature]
 Surveyor to Lloyd's Register of Shipping.

TUE 14 JUL 1942
 See lco. S.E. 2090
 © 2020 Lloyd's Register Foundation