

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME STEEL S.S. "EDELLYN"Report Pbl.No. 3363

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey

When due

The Downston Pump has been dispensed with for the present.

Some temporary wood deckhouses have been erected on Shelter Deck, but they will probably be removed within the next four months.

* 100 A.1. (steel) "Shelter Dk. with freeboard".

2 Dks. (steel) and Shelter Dk. (steel).

Cell DB 380' 1831 t. Tween Dk. tanks in E & B space 36' 405 t.

FPT 281 t. APT 271 t.

FK. 10 BH to Shelter Dk. pt. cem. A & C.P.



© 2020

Lloyd's Register
Foundation

002289-00 2297-0118

Corresponding Draught

51 ft. 1 ins.