

(Req. 1a.)

Groningen district.

(Received at London Office.....)

No. 126 Place Foxhol.

RECEIVED

21 FEB 1950

Date 14th February, 1950.

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 88 building by Messrs. N.V. Schw. "Foxhol" v.h. Gebr. Muller, for Messrs. B. and K. Pronk, of 370 Tons. Length 43.- M., Breadth 7.70 M., Depth 3.20 M. intended to be Classed *100A1.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—


"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers M.A.N., Augsburg.

Boiler Makers -

To the Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street, London, E.C.3.

Signature.....



NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—

"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

Auth
CSP 73

002305-002319-0069

Lloyd's Register
Foundation

Referred to the Chief ~~Ship~~ Surveyor
and the Chief Engineer Surveyor.

W.B.

Referred to Mr. Betts.
Also for Mr. ~~Hunnex~~ to note

Noted
W.B.
Roll

7



© 2020

Lloyd's Register
Foundation

re
ed
ted

11 m
and
& decks have been repaired as required and a found right.

St
Fla
be
(b)
GENERAL

Steering
Ceiling
Cargo H
Size of H
Number
and/or