

Do. of Poop
Do. of R.Q.Dk.
Do. of Bridge Ho
Do. of Forecastle
Do. of Houses on
Do. of excess of H
Do. above Crown
Engine Room

5c, 12, 16.

Baltic

F.E.

Received by Chief Ship Surveyor 12.8.18

Received from Chief Ship Surveyor

VESSEL'S NAME *Shell's War Loppice*

Rpt. *SL*

No. 27304

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 72

Depth "d" 20.87

Framing: Table No. 3 page 11

Description *Bulk angle as appraised*

Longitudinal No. 23832

Proportions $\frac{\text{Length}}{\text{Depth}} = 10.03$

Deck Deck Sheerstrake as appraised

Don'ta pump & Vadege Anchor dispened with as appraised in Standard Vessels
Large battens not fitted

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *100 A-1 (Steel per recommendations)*

100 (Steel)


cell AB 276' 734C. F.P.T. 105C. A.P.T. 122C

FK. ft. Cam. Lgds wcep. P 33' B 98' F 28'

The Certificate of Classification, to be endorsed
"Cargo battens not fitted," and the same
notation to be printed in the Register Book.

12.8.18

001330-001339-0132



© 2020

Lloyd's Register
Foundation

BEAMS, PO

" A

BEAMS, BR