

Dear Sir,

Further to our letter of yesterday's

S.....  
and )  
..... )  
side )  
rom )

5m.7.30

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Stt T.S. " ABEILLE N° 16 " Report LK No. 19278

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey 1<sup>st</sup> Entry When due Revised Rules


✠ 100 A.I. (Steel) for Towing Services

1 D\* (Stl - Leaks)

F.P.T. 120, A.P.T. 340.

B.K 7 1/2", 3 B.H, Com, Lloyds A.V.P.

34.  
30.  
AME.



© 2020

S.  
29.12.30

002362-002373-0027

002362-002373-0027

Lloyd's Register Foundation

id Floors, thickness and spacing

" Are Frame and Reversed Frame joggled ?

" Floor breadth and thickness at

Bridge Deck, Angle, E or F

Spacing