

002374-002384-0137

Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

NAME St S S ELMFIELD

Report Lin

No. 89215

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Survey 1<sup>st</sup> Entry

When due \_\_\_\_\_

100 A.I. (Steel).

dk (Stl) "Well dk"


2Tf 19' 48t, F.P.T. 12t, A.P.T. 21t.

S.K 6 $\frac{1}{2}$ ", H.B.H, Cem, Lloyd A.C.P. machy aft

2 85', B 9', F 23'.

The Certificate of Classification to  
contain "Cargo battens  
ed" and the same notation to be  
ted in the Register Book.

Whyas should be requested to forward the forging reports



© 2020

Lloyd's Register  
Foundation

26.10.25