

2m.351

The class is subject to electric lighting in Nos.1,2,4 & 5 holds being dealt with.

5 E

30 MAY 1951

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

VESSEL'S NAME

"ANGUSDALE"

REPORT

Rot.

33435

Mtl.

No. 8535

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey

~~DAMAGE & WEAR AND TEAR.~~

Docking.

Propeller changed with spare.

Alterations effected to pumping arrangements in accordance with approved plan.

It is submitted the vessel is eligible to remain as classed. ~~with~~

~~word of survey~~

as recommended, subject as above

002418-002426-0152



© 2020
Lloyd's Register
Foundation