


COPY

LLOYD'S REGISTER OF SHIPPING



Port H A M B U R G

18th May, 1960

This is to Certify that I have

Surveyed the Machinery of the M.S. "ARISTID", 12151 tons gross of
Vaduz, whilst the ship lay in dry dock and afloat at Hamburg on
the 30th June, 1959 and subsequently for General Examination for
a voyage as an unclassified ship to Piraeus

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following

Survey Records be made in the Supplement to the Register Book
DBS 5.60, when all boilers except the port Donkey Boiler have
been examined and their safety valves adjusted under steam.

XX
and that her Machinery Classification Record be continued in the Book.
without special condition regarding circuit breaker to be fitted
to 75 kW starboard aft generator at first opportunity, but subject
to Main Engine No.2(starboard) crankpin being specially examined
by the end of August 1960 (3 months limit).

Parts now examined:

(C.S. Items only)

Starboard and port Main Engine crankshafts shrunk fit controlled.

K.H. Fedderwitz

(K.H. Fedderwitz) Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
KL "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

002442-002448-0014