

D. L. H. COLLINSON, LTD.

CONSULTING ENGINEERS AND MARINE SURVEYORS

COLLINSON, M.I.N.A., M.I.Mar.E.
Late Senior Surveyor to
Lloyd's Register of Shipping
J. L. COLLINSON

TELEPHONE & TELEGRAMS :

TORQUAY 4193

2 DANBY LODGE

LINCOMBE DRIVE

TORQUAY

16th January 1960.

S. S. "CABLE ENTERPRISE".

18 JAN 1960

Dear Sir,

This Vessel is laid up at Plymouth with surveys overdue and I am writing on behalf of the Owners to ask what are the Committee's minimum requirements to enable a load line certificate to be issued for the voyage to Italy under her own steam. Any surveys for reinstatement in class could be carried out on arrival.

I conclude a boiler survey, and examination in dry dock and the acceptance of the essential machinery under working conditions is all that would be required.

Yours faithfully,

The Secretary,
Lloyd's Register of Shipping.
LONDON.



Lloyd's Register
Foundation

002442-002448-0163

①

SR/ER.

CLASSIFICATION

H
F ✓

COPY TO FBI

Submitted slits be generally
examined in dry dock in accordance
with Ci. 1459. Taking into account her age
and the length of time laid-up, and found
or placed in satisfactory condition for the enclosed
voyage as an unclassified slits.

~~HP~~
19.1.60

also 2 main
need be done. G.E

bearings
as per (1959)

HP cyl. valve to be opened on 9/1/60
if found satisfactory no further opening out
MBB and TS to be held

19/1/60

See separate endmt at R
20.1.60



© 2021

Lloyd's Register
Foundation