


COPY

LLOYD'S REGISTER OF SHIPPING

5862



Port DJAKARTA

13th May 1961.

Port Boiler

This is to Certify that I have

Surveyed the Machinery of the S.S. " BONITA " 2958 tons gross
of Panama whilst afloat at Tandjung Priok on 10th May 1961
and subsequently, on account of Port Boiler Repairs,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

No alteration

and that her Machinery Classification Record be continued in the Book,
subject to all conditions at present attached to the vessel's
class being dealt with as previously recommended.

Parts now examined:

(C.S. Items only)

NOW DONE:- Port Boiler:- Back end plate found cracked
below the Centre and the Port manhole apertures
and now veed out and welded for "24" and "12"
respectively.

C. Ritchie
Engineer Surveyor to Lloyd's Register
C. Ritchie

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

002449-002456-0070

© 2020
Lloyd's Register
Foundation