

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex  
Telex No.: 24305

Telephone: ROYal 9166

Enclosure

25th July, 1960.

n (S)  
BS

Dear Sirs,

Motorship "BURSA"

The Society's Surveyors at Singapore have reported that this ship was under survey in May/June when the shell and deck plating was drill tested.

An examination of the thickness of the upper deck and shell plating over the cargo tank length as shown on Singapore Harbour Board's drawing No. R/1494, a copy of which is enclosed, indicated that renewals will be necessary at the Special Survey and these renewals have been indicated in red on the drawing for your guidance, it being assumed that the drillings are representative of the general condition of the plating.

Recommendations for renewals of plating outside the cargo tank length and any amendments to the renewals indicated at present that may be necessary are at the discretion of the Surveyors at the time of the survey.

Yours faithfully,

Deputy Clerk to the  
Classification Committee.

c.c. SINGAPORE

Messrs. Shell Tankers, Ltd.,  
Ibex House,  
Minories,  
London E.C.3.

Lloyd's Register  
Foundation

002457-002454-0243