

1E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

ANNA KNUDSEN.

Rpt.

Tot.

No.

886.

marks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

e of Engine

old Dupuis 45C 5A

If Boilers fitted with forced draught

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

Yes


No.

This vessel's machinery appears to have been built in accordance
with the Rules and the approved plans, and it is submitted she is
eligible to be classed

+ dmc 12-31

200/504.

259 57/1/31



© 2020

Lloyd's Register
Foundation

002471-002476-0049

559
431
97 LR