

11 MAR 1959

Received from Chief Ship Surveyor.....

SHIP'S NAME "BRITISH ADMIRAL" REPORT Lon. No. 139755

GB

Outstanding Conditions of Class: Subject to indented side shell plating F.5, G.5, 6 & 12 (s.g.f) also H.12 & 13 (p.s.) being dealt with by the Special Survey.

Endorsement of Certificate (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (B) due 5,59. Postponement until 7,59 approved 1,59.

Location of Present Survey: (Afloat ~~and in dry dock~~)

Examination afloat after grounding.

Special Features:

Interim Certificate in order (Yes-~~No-None~~)

Items Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: 7,59.

Recommendation:

SUBJECT as above, but further ACTION be DEFERRED for examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L. Drydocking(grounding).

IN S.R.L. APPENDIX Indents in shell plates H.6 (p.s.f) F.4 (s.s.f) and poop side plating (p.s.).

© J. J. J. 10/3/59



Lloyd's Register Foundation

Blk (new)

Date of Committee THURSDAY - 6 JUL 1961

Committee's Minute

To be broken up