

Chief Surveyors _____

Received from Chief Surveyors _____

SHIP'S NAME Steel Screw M.S. "BRITISH POWER" Report Gls. No. 57800

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

of Survey _____ First Entry _____ When due _____ --

100A1 'Carrying petroleum in bulk'

1 Dk. 2nd Dk. clear of cargo tanks, Longitudinal framing at bottom and
Cell. DB u E '78' 175t, DTf 34' 434t, FPT 224' APT 200t. at deck.

FK, 17 BH, pt. Cem., pt. Asp., Lloyd's A & CP.

P 105', B 43', F 45'.

Machy. aft.



30.12.36

Lloyd's Register
Foundation

002477-002484-0193