

26 SEP 1957

Received from Chief Ship Surveyor.....

SHIP'S NAME "BADARPUR" REPORT Krh. No. 2666

Outstanding Conditions of Class:

Subject to sternframe (E.W. 5,54)  
and top section of the rudder steadiment bearing being  
specially examined and dealt with as necessary next drydocking,  
also to indented side shell plating etc. in way of after cofferdam  
(s.s.) being dealt with as necessary next drydocking by 1,58.

Endorsement of Certificate (~~As before~~ or None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Examination afloat after grounding.


Recommendation:

SUBMITTED ACTION be DEFERRED for examination  
in dry dock after grounding, subject as above.

~~KE Item.~~ Subject

INSERT IN S.R.L.  
Drydocking (grounding).

NOTE:- Diver's Report not yet received.



© 2020

04.12/9/57  
Lloyd's Register  
Foundation