

LOYD'S REGISTER  
Received  
7-APR1943  
Amcl.  
LONDON

Room 6, 2nd Floor,  
Dorland House,  
Regent St., S.W.1.

6th April, 1943.

The Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch Street, E.C.3.

Dear Sirs,

A/MS 337  
"Empire Cavilier"  
Laing's No.743

The working bronze propeller of this vessel has recently been removed while the vessel was in dry dock on the Mersey, to enable certain alterations to be effected under the direction of Dr. Hughes of the National Tank, with a view to curing the excessive singing. In order to avoid any possible delay and occupation of the dry dock for a longer period than absolutely necessary, it was decided to fit the spare cast iron propeller meantime, and replace the bronze propeller at a later opportunity. This project, however, had to be abandoned, as it was found that the spare propeller did not fit the vessel's shaft.

It is assumed by the Department that a spare propeller supplied to a new vessel inspected and classified by Lloyd's, and carried in accordance with the Society's Rules will fit the shaft of the vessel and we should like to have your comments on the matter.

Yours faithfully,

*J. H. G. G. G.*

for D.M.B.

002490-002497-0080



Referred to the Chief Engineer Saratoga

7 - APR 1943

Also for Mr. Sladden to note.

*Surveyor's remarks.*

*8/4/43*

*1/2 Hpc  
his 1242 dam  
24 ft*

*In the low*



© 2020

Lloyd's Register  
Foundation