

ived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SEL'S NAME *Empire Cavalier*

REPORT

Spec. No. 100,885
Mod. No. 17297
Sld. No. 335-44

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Rec Engine & S.C.S.A.
8 Cy. 25 $\frac{1}{2}$ " - 55 $\frac{1}{2}$ "

~~If Boilers fitted with forced draught~~

Tail Shaft. If fitted with a continuous liner

If fitted with an outside gland of

approved type

Yes

No

This vessel's machinery appears to have been built in accordance
 with the Rules and the approved plans, and it is submitted she is
 eligible to be classed *+ N.O.W.T. Specification*
+ LMC 11.42.

DB & 1 WTDB 180 lb.

Inspt. in S.R.L.:- Steam pipes marked
Benemer Steel on flanges to be
examined after four years service.



© 2020

Lloyd's Register
 Foundation

002490-002497-0084