

Report No.

THE BRITISH CORPORATION REGISTER OF SHIPPING AND AIRCRAFT MACHINERY

No. in Reg. Book -11-

Port Singapore

S.S. ASPHALION

20th October 19

Test of Main Injection Valve Chest Survey held* Singapore Harbour Board

Owners Electric Lighting? Kws.

Engines :

Description Made by When
Cylinders, No. each Eng. Diars. Stroke Cub. Ft. each L.P. Cyl.

Boilers :

Main, No. & Description W.P. Made by When
Aux. M. Do. W.P. Made by When
Donkey

Main Steam Pipes, Material Welded, Brazed, Seamless When Tested
Propeller Shaft, Diar. under Liner Description of Liner When Drawn
Class M.B.S. S.S. Type No. Due Boiler Survey Due M.S. Due

* Insert name of Dry Dock ; or where, if afloat.

Indicate, clearly, repairs actually carried out and distinguish between those consequent upon damage and those due to wear and tear. All work in connection with special survey must be detailed in the same order as in the rules. State if Boilers (including Donkey Boilers) were examined internally at the same time giving reasons if this has not been done.
State if a report on the hull accompanies this report. If not give reasons.

First Visit Last Visit Boilers and Engines then in
No. of Visits

Fees £ Advised

Expenses £ Paid

..... Chief Surveyor.



© 2020
Surveyor to the British Corporation
of Shipping and Aircraft
Lloyd's Register
Foundation