

Received from Chief Ship Surveyor 7 APR 1959

SHIP'S NAME "BRITISH SWORDFISH" REPORT Sws. No. 26454.
AR.

Outstanding Conditions of Class:

Subject to repairs to shell plates H.4 & 7
(p.s. from fwd.) being examined and dealt with as necessary next S.S.
and to indented shell plate K.4 (p.s.f) being examined and dealt
with as necessary by the S.S.

Endorsement of Certificate (As before ~~or None~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking; Temporary repairs; W & T repairs to bottom shell plating
in way of pump room and bilge strake plating (P&S) in accordance
with attached plan.

Recommendation:

SUBMITTED record of 'DS 3,59' be assigned SUBJECT ^{as above &} to bottom
shell plating in way of pump room and bilge strake plating (p&s)
(wasted & doubled) being specially examined and dealt with as necessary
next drydocking.

DS 3,59. Subject.

IN S.R.L. APPENDIX.

Indents in shell plating (P & S)
Nos. 3 & 4 keel plates aft waved.

✓



75
© 2020
31-3-59

Lloyd's Register
Foundation