

29 JUN 1959

Received from Chief Ship Surveyor

SHIP'S NAME "BERKEL" REPORT Skm. No. 12052
VC

Outstanding Conditions of Class: SUBJECT to set up No.2 keel plate from forward being further examined and dealt with as necessary next drydocking,

S.R.L. — Appendix. (~~As before~~ or None)

Nature of Present Survey: (Afloat and in dry dock)

Docking; Repairs on account of Ice damage.

Recommendation: SUBMITTED record of DS 5.59. as assigned as recommended
SUBJECT as above, and to indented shell plating in E. & F. strake (p&s.f) being specially examined and dealt with as found necessary by the Special Survey

As now. SUBJECT.

|| ENGINEERS TO ~~NOTE~~ THIS REPORT. ||

© 2020



Lloyd's Register
Foundation