



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

95, Bothwell Street, Glasgow, C.2

Telegrams: Register, Glasgow

Telephone: Central 6491 (4 Lines)

RECEIVED

15th November, 1955

16 NOV 1955

Dear Sir,

Ans'd

I have to acquaint you that when Greenock Report No. 25504 on the tug "BRIGADIER" was before the Scottish Sub-Committee of Classification at their Meeting today, the Chairman instructed that your attention be drawn to the oil gland which has been fitted to the tail shaft, in order that the necessary action could be taken by you respecting the "O.G" notation and also informing the Owners.

I might add that the Owners' Superintendent has had the position explained to him, and he realises that they will not now get the notation "O.G" for this tug.

Yours faithfully,

The Secretary,
LONDON.

W. S. Liner 2020
Secretary to the
Scottish Committee.

002522-002528-0191

Lloyd's Register
Foundation

H

CLASSIFICATION

H.

Before RB altered
It is not understood how
some map was assigned "OB" in
357. is no longer has been changed
date submitted this 355. since
(a) since
(b) since

man
1. 1. 11

© 2020

Lloyd's Register
Foundation