

*Assiduity*

(Received at London Office.....19....)

No. 608 Place Newbury

Date March 28th 1930

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to inspect one 250/275 bhp Marine Oil Engine during construction at our works

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connexion therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

For & on behalf of

THE PLENTY-STILL OIL ENGINES LIMITED.

*AWJ*

MANAGING DIRECTOR.

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

002536-002542-0073

A.  
1



© 2020

Lloyd's Register  
Foundation