

C O P Y

22nd August, 1958.

STERDAM


74, 87, 89 - As recommended.

20 "BARKENTINE" - As recommended.

I shall be glad if you will inform the Owners that keel plating dships drilled and gauged $17\frac{1}{2}$ mm will require to be renewed, and t the keel plating adjacent should at the same time be drilled so t the Surveyors concerned may satisfy themselves that this is in er.

With regard to the deck drillings, it is considered that the st strake inboard of the deck stringer plate, frame 105-116, now ged as 9 port and $8\frac{1}{2}$ starboard should be renewed. The remaining llings are in order.

57 "ULYSSES" - As recommended, a notation of S.S. Sng. - 11,57 ing been assigned.



© 2020

Lloyd's Register
Foundation

002536-002542-0189