


"BARKINTINE"

Bottom drillings examined and considered in order subject to renewal of keel plate amidships as recommended by Ship Reports Dept.

With regard to the deck drillings it is considered that the first strake inboard of the deck stringer plate frame 105 - 116 now gauged as 9 port and 8½ starboard, should be renewed. The remaining drillings are in order.

Reports Dept. re internals.

A handwritten signature in dark ink, appearing to be 'J. B. W.', written over a horizontal line.

18th August, 1958.



© 2020

Lloyd's Register  
Foundation

002536-002542-0190