

I am returning herewith Greenock Machinery

Report No. 18319 on the S. S. "TONGARIRO", and in reply
to your letter of yesterday's date I have to say that the

002543-002549-0017

s/s "Tongariro"

Gls. 44399.

It is submitted that the Glasgow Surveyors be
requested to state whether they are correct in
reporting that the Superheater safety valves ~~is~~ is
adjusted to 107 pounds per square inch.

Lr fls 18/3/25

185th
See Gls. No. 19/3/25



© 2020
AWD
5/3/25
AWD

Lloyd's Register
Foundation

ve or below
a spigot and
No. of Cer
No. and
Are they
M
rip. of rivetin
plates or wi
hole in shell
terial
No. o
ack
Work
rules
es
of Front