


157676

COPY

## LLOYD'S REGISTER OF SHIPPING

Port LIVERPOOL.13th October, 1961.This is to Certify *that I have*

*Part*  
 Surveyed the Machinery of the *m.v.* "FORDFIELD" 561 gross tons of Liverpool  
 while in Clarence Drydock,

and that I will transmit to the Committee of Lloyd's Register of  
 Shipping, London, a Report stating that all recommendations made by  
 me in connection therewith have been carried out to my satisfaction; also  
 that I will Recommend that in the case of this Vessel ~~the following~~  
~~Survey Records be made in the Supplement to the Register Book~~

~~and that her Machinery Classification Record be continued in the Book.~~

**Parts now examined:**

(C.S. Items only)

Main Engine

All cylinders, covers, pistons, rods, valves and gear.  
 All connecting rods, top ends, crankpins and bearings.  
 All journals and bearings.  
 Fresh water and sea water engine driven pumps.

**Sea Connections.**

Both Main Air Receivers.  
 Engine tested manoeuvring.

P. H. Ferri

Engineer Surveyor to Lloyd's Register

## KEY TO ABBREVIATIONS


ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

002543-002549 0042



© 2020

Lloyd's Register  
Foundation

NOV 1961