

3
8th February, 1952.

Dear Sirs,

"BEVIN PALM"

We have to inform you that the above vessel has been in this port for adjustment of safety valves after overhaul at Owners request.

The saturated and superheater safety valves of the centre boiler, and the saturated safety valves of the port boiler have been adjusted. The port boiler superheater safety valve and starboard boiler saturated and superheater remain to be adjusted.

It is understood that the vessel is proceeding to your port where the remaining safety valves will be adjusted, and we shall therefore be glad if you will kindly give the case the necessary attention.

Yours faithfully,


THE SURVEYORS,

Per:

David F. Brooke Sm. H.

The Surveyors,
ROTTERDAM.

002543-002549-0208



© 2020

Lloyd's Register
Foundation