

Chief Surveyors.....

Received from Chief Surveyors.....

L'S NAME BENIN PALM REPORT Liu. No. 133944

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Survey LMC & Alterations. When due.....

Both old boilers removed & replaced by three new boilers.

Noted.

The Liverpool Surveyors should be informed the correct MN appears to be 602,

made up as follows:-

$$54 \left(\frac{(57 \frac{1}{16})^2 \sqrt{39 \frac{3}{8}}}{100} + \frac{468}{6} + \frac{9990}{12} \right)$$

Agreed. See his bo.
13/11/57

and their comments are desired.


Register Book to read:-

220 lb. (Spt) F.D.

9990 sq. ft.

602.

Ent
1/11/57



© 2020

002543-002549-0213

Lloyd's Register
Foundation