

COPY

LLOYD'S REGISTER OF SHIPPING



Port..... Fremantle...W.A.

..... 13th March, 1961.

This is to Certify *that I have*

Surveyed the Machinery of the M. TANKER "BRITISH PATIENCE" of
LONDON, for temporary repairs to electric wiring between
poop and midship accommodation,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
~~*Survey Records be made in the Supplement to the Register Book*~~

~~*and that her Machinery Classification Record be continued in the Book.*~~
~~*subject to permanent repairs to electric wiring from poop to*~~
~~*midship accommodation at next Dry Docking and to any other*~~
~~*conditions at present attached to the class of the machinery*~~
~~*being dealt with as previously recommended.*~~

Parts now examined:

(C.S. Items only)

F. K. L. Birk
(Sgd.) F.K.L. Birk.

Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tallshaft Survey
ES	Engine Special Survey	TS (CL)	Tallshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tallshaft Renewed
MES	Modified Survey of Oil Engines	TS (GG)	Tallshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."