

Rpt. 9 MS

18 JUN 1959

Date of writing report 29-5-59

Received London

Port of ROTTERDAM

No.

Survey held at Capelle a.d. IJssel

No. of visits 1

First date and

Last date 19-5-59

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 53878. Name M.V. "BERMUDA" Gross tons 199 Date of build 1932
 Owners Redery "Bermuda" Managers Fa. A. van Dijk Port of Registry Delfzijl
 N Engines made 50 By Masch. Kiel A.G. Type Oil Eng. 4S.A. M.N. 24
 No. of Main Engines 1 No. of Screws 1
 No. of Main Boilers -- W.P. --
 No. of Aux./Donkey Boilers -- W.P. --
 Surveyed Afloat or in Dry Dock slipway
 Nature of Survey Condition: Damage Repairs
 Was Damage Report issued? NO Int. Cert.? attached
 Last Report (For Head Office only)

Records of Survey & Special Notations as per Register Book

Hull	Machinery
B.S. coasting service	M.B.S. 4-57
Dock 11-58	T.S. 3-58 N. O.G.
S.S. Hrl. (Dr.) 4-57	

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers good Wear Down of Stern Bushes a fit Oil Glands tight Sea Connections
 Fastenings good Has Screwshaft been drawn? NO Date of Examination -- Has Shaft been changed? no
 Has Shaft now fitted been previously used? -- Has Shaft now examined/fitted a continuous liner? -- Approved oil gland? --

MAIN ENGINES (Recip. Steam or I.C.)

PORT

STARBOARD

1 Cyls., Covers, Pistons & Rods

2 Valves & Gears

3 Connecting Rods, Top Ends & Guides

4 Crankpins & Bearings

5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods

7 Connecting Rods & Top Ends

8 Crankpins & Bearings

9 Journals & Bearings

10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods

12 Connecting Rods & Top Ends

13 Crankpins & Bearings

14 Journals & Bearings

15 Levers

16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS The Machinery of this vessel is in good condition and eligible in my opinion to remain as classed without fresh records of Survey.

TUESDAY - 7 JUL 1959

Date of Committee

Decision

Noted for Header

40m, 457. T. (MADE AND PRINTED IN ENGLAND.)

Engineer Surveyor to Lloyd's Register of Shipping
G. Bons

© 2020

Lloyd's Register
Foundation

002550-002558-0203

not
required

If certificate is required state where to be sent.

Has a Survey also been held on Ship?
 If so, is the Report sent now, or when will it be sent?

32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers
36 Lub. Oil Coolers
37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety devices—Main
40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators
43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery
45 Windlass
46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)

Table with 4 columns: PROPULSION, PORT, STARBOARD, ELECTRICAL EQUIPMENT. Rows include Generators, Exciters, Air Coolers, Motors, Control Gear, Cables, etc., Insulation Resistance, Insulating Oil Test, Overspeed Governors, Magnetic Couplings, Air Gap, and Auxiliary Equipment (Generators & Governors, Motors, Switchboards & Fittings, Circuit Breakers, Cables, Insulation Resistance, Steering Gear Generators and Motors, Navigation Light Indicators).

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)
MAIN
AUXILIARY, DONKEY or PRESS
Superheaters
Safety Valves
Mountings, Doors & Fastenings
Safety Valves Adjusted to Sat. Spt.
Boiler Securing Arrangements
Main Economisers
Exhaust Gas Heated Economisers
Steam Heated Steam Generators
Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules?
Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules?
Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)
Main
Auxiliary (over 3 in. bore)
Were Copper Pipes annealed?
Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)
Damage to propeller stated sustained through contact with canal bank in April 1959 on voyage from Alkmaar to Den Helder.

Propeller tips found slightly bent, now faired in place.

Locking propeller blades faired.

It is submitted that this vessel is eligible to remain as CLASSED.

M. J. Jansen
30.9.59

LEAVE THIS SPACE BLANK

Survey fees
Damage fee Fl. 25,-
Expenses
Date when A/c rendered 15 JUN 1959

