

by Chief Ship Surveyor

Received from Chief Ship Surveyor

'S NAME Steel S.S. AYANYILLE

Rpt. Sou

No. 10456

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

1<sup>st</sup> Entry.

This vessel has left for Sunderland to have machinery installed. To complete the survey. The engine and boiler casings are to complete, pillars to fit in machinery space, Downton Pump to fit and test, spare tiller and relieving tackle to fit, & steering gear and windlass to test.

The Sunderland Surveyors should be informed and requested to forward a report on form N° 8 when the survey is completed

The Southampton Surveyors should be requested to state whether the record of "Cem" or "pt. asp" should be made in this case

new entry  
30/7/20

30.7.20



© 2020

Lloyd's Register  
Foundation

30-7-20

002568-002576-0042