

4 E

Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

NAME "ARCTIC VIKING"

Rpt.

Hul. 53830

Hpl. No. 18862

arks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


Survey ~~-REPAIRS-TO-ENGINES-AND-BOILERS-DUE-TO-DAMAGE-THROUGH~~

A new engine constructed under Special Survey, new auxiliary machinery and pipe lines have been installed after war damage and sinking.

Boiler removed to shop and extensively repaired with new material as necessary and boiler refitted on board and converted to burn oil fuel.

Some minor items remain to be completed at Hull.

IT IS SUBMITTED action be deferred to await report from Hull.



© 2021

Bell

16.9.47.

Lloyd's Register
Foundation

002577-002582-0076