

Memorandum

builders. Messrs. M.V. Fak Fak

Yard No.

neers. Messrs.

Engine No.

It is submitted The plan of revised pumping arrangements has been examined but owing to the lack of information on the plan it cannot be fully dealt with. Further, the oil fuel arrangements as shown on the plan are as shown on the original plan approved 3/4/48 but without the amendments which were indicated on ~~that plan~~ the latter.

Accordingly, the Surveyor should be asked to confirm that :-

- (1) The number and sizes of bilge suction and pumps on bilge service are not less than those which were on the vessel before the installation of the new engines.
- (2) The amendments to the oil fuel system which were indicated on the plan approved 3/4/48 have been carried out.

turn plan.

tain copy.

2020  
R  
Lloyd's Register  
Foundation

002542002601-0055